



12.0" Radius, 2.0" Border, White on Green;  
 [W EST] E Mod 2K; [S OUTH] E Mod 2K; [Freeport] ClearviewHwy-5-W; [Bloomington] ClearviewHwy-5-W; Arrow 160 - 35.0" 45°;  
 Table of letter and object lefts.

W	E	S	T	39	S	O	U	T	H	
64.0	83.4	94.4	105.9	132.8	183.8	231.8	247.4	260.4	272.3	
F	r	e	e	p	o	r	t	20		
75.0	89.9	101.3	117.8	135.0	151.4	169.2	179.6	231.6		
B	l	o	o	m	i	n	g	t	o	n
48.9	64.4	73.6	90.8	108.6	132.5	142.0	158.4	174.5	186.5	204.4

SN-021  
 2C101U020L024.8

**ENGINEERING CONSULTANT**  
**Clorba Group, Inc.**  
 CONSULTING ENGINEERS  
 8007 North Cumberland Avenue, Suite 402  
 Chicago, Illinois 60636  
 Tel. 773.775.4009 Fax 773.775.4014  
 Email: info@clorba.com

USER NAME = jattanaseo	DESIGNED - JPA	REVISED -
	DRAWN - JPA	REVISED -
PLOT SCALE = 10,0000' / 1" =	CHECKED - MJL	REVISED -
PLOT DATE = 1/31/2014	DATE - 1/31/2014	REVISED -

**STATE OF ILLINOIS**  
**DEPARTMENT OF TRANSPORTATION**

**SIGN STRUCTURE REPLACEMENT**  
**SIGN PANEL REPORT - SN-021**

SCALE: N.T.S. SHEET NO. 1 OF 7 SHEETS STA. TO STA.

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
VAR.	.	**	45	13
• D-2 OVD SIN STR REPL 14-27			CONTRACT NO. 46288	
ILLINOIS FED. AID PROJECT				