



**DECK REPAIR PLAN**

**NOTES**

Quantities and repair areas shown are estimated. Actual areas to be determined by the Resident Engineer and recorded on As-Built plans.

**LEGEND**

-  Deck Slab Repair (Partial Depth)
-  Deck Slab Repair (Full Depth)
-  Protective Shield

**BILL OF MATERIAL**

Item	Unit	Total
Deck Slab Repair (Partial)	Sq. Yd.	25
Protective Shield	Sq. Yd.	829
Deck Slab Repair (Full Depth Type II)	Sq. Yd.	32

<b>CEC</b> Cummins Engineering Corporation Civil and Structural Engineering	JOB = 2236.09	DESIGNED - AAN	REVISED -
	FILE = 0540069-72E11-003-DeckRepair.dgn	CHECKED - ENV	REVISED -
	DATE = 2/12/2013	DRAWN - SJS	REVISED -
		CHECKED - MDC	REVISED -

**STATE OF ILLINOIS  
DEPARTMENT OF TRANSPORTATION**

**GENERAL PLAN  
STRUCTURE NO. 054-0069**

SHEET NO. 3 OF 9 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
55	D6 LOGAN CO BR 2011-1	LOGAN	429	377
			CONTRACT NO. 72E11	

ILLINOIS FED. AID PROJECT