



LOCATION #1 - FAI 55 (I 55)  
EASTBOUND AND WESTBOUND  
STA. 556+10 TO 571+09.34  
STA. EQ. - 571+09.34bk = 569+32.15ah  
STA. 569+32.15 TO 635+29.82  
STA. EQ. - 635+29.82bk = 634+02.39ah  
STA. 634+02.39 TO 651+19

LEGEND

- 1 EXISTING STABILIZED SHOULDER 5"
- 2 EXISTING CONTINUOUSLY REINFORCED PCC PAVEMENT, 8" E.B./7" W.B.
- 3 EXISTING LONGITUDINAL JOINT
- 4 EXISTING GRANULAR MATERIAL 4"
- 5 EXISTING AGGREGATE SHOULDERS, TYPE B
- 6 EXISTING BITUMINOUS SHOULDERS 3" E.B./7" W.B.
- 7 EXISTING BITUMINOUS CONCRETE BINDER COURSE, SUPERPAVE, 1<sup>3</sup>/<sub>4</sub>"
- 8 EXISTING BITUMINOUS CONCRETE SURFACE COURSE, SUPERPAVE, 1<sup>1</sup>/<sub>2</sub>"
- 9 EXISTING C.R.P.C.C. PAVEMENT 8"
- 10 EXISTING BITUMINOUS SHOULDER 8"
- 11 EXISTING STABILIZED SUB-BASE 4"
- 12 EXISTING BITUMINOUS SURFACE COURSE 4<sup>1</sup>/<sub>2</sub>"
- 13 EXISTING BITUMINOUS SHOULDER 3<sup>1</sup>/<sub>4</sub>"

QUANTITIES  
FAI 72/FAP 662 (I 72/IL 4/VETERANS PKWY  
SECTION D 6 PAVEMENT PATCHING  
SANGAMON COUNTY