



ALIGNMENT DATA

RUNWAY/TAXIWAY	DESCRIPTION	STATION	PROJECT COORDINATES	
			NORTHING	EASTING
ALIGNMENT 200	BEGINNING OF ALIGNMENT 200	200+00	1800480.06	1050956.27
	END OF ALIGNMENT 200	210+00	1800529.66	1051955.04
ALIGNMENT 300	BEGINNING OF ALIGNMENT 300	300+00	1800338.12	1050963.31
	END OF ALIGNMENT 300	310+00	1800387.65	1051962.08
ALIGNMENT 400	BEGINNING OF ALIGNMENT 400	400+00	1800521.07	1051782.03
	END OF ALIGNMENT 400	403+00	1800820.93	1051722.84
ALIGNMENT 500	BEGINNING OF ALIGNMENT 500	500+00	1800528.12	1051923.95
	END OF ALIGNMENT 500	503+00	1800827.97	1051914.75

CURVE DATA

CURVE #	CENTER	P.C.	P.T.	CURVE #	CENTER	P.C.	P.T.
201	200+38.40 (100.0' RADIUS) 290.0' LT	200+38.40	200+48.40 290.0' LT	301	301+16.13 (62.5' RADIUS) 75.0' RT	300+76.76	301+16.13 12.5' RT
202	200+82.40 (100.0' RADIUS) 290.0' LT	200+82.40	200+72.40 290.0' LT	302	307+17.89 (62.5' RADIUS) 75.0' RT	307+17.89	307+80.39 75.5' RT
203	200+38.41 (100.0' RADIUS) 183.4' LT	200+38.21 173.4' LT	200+48.41 183.4' LT	303	308+60.16 (62.5' RADIUS) 36.0' RT	307+97.66	308+60.53 26.5' LT
204	200+82.41 (100.0' RADIUS) 183.0' LT	200+82.21 173.0' LT	200+72.41 183.0' LT				
205	207+53.19 (62.5' RADIUS) 75.0' LT	207+53.19	208+15.69 73.8' LT				

ALIGNMENT AND CURVE DATA

REHABILITATE NORTH HANGAR PAVEMENTS,
 IDA No. LOT-4020 AIP No. 3-17-0140-B48



Hanson Professional Services Inc.
 815 Commerce Drive Suite 200
 Oak Brook, Illinois 60523

Hanson No. 10A0072
 Filename 07-ALIGNMENT-CURVE DATA.DWG
 Scale 1"=40'
 Date APRIL 22, 2011

LAYOUT	KMS	02/25/11
DRAWN	KMS	02/25/11
REVIEWED	RMH	4/22/11



Chicago-Romeoville Airport
JOLIET REGIONAL PORT DISTRICT

1 George Michas Drive
 Romeoville, Illinois 60446
 Telephone: 815.838.9497
 Fax: 815.838.9524

DATE	REVISION

LE042