

FULL DEPTH REPAIR

NOTE:

ALL BARRIER WALL REPAIR SHALL BE COMPLETED IN ACCORDANCE WITH STATE STANDARDS 637001 AND 637006 AND SECTION 637 OF THE STANDARD SPECIFICATIONS AND AS SHOWN ON THE PLANS, ALL PROPOSED DOWEL BARS AND TIE BARS SHALL BE DRILLED AND GROUTED IN PLACE, REINFORCEMENT SHALL BE INCLUDED AS SHOWN IN STANDARDS 637001 AND 637006 AND DESCRIBED IN SECTION 637 OF THE STANDARD SPECIFICATIONS EXCEPT WHEN A REINFORCEMENT CAGE IS ENCOUNTERED. IN SUCH A CASE, THE CONTRACTOR SHALL REMOVE THE DAMAGED PORTIONS OF THE CAGE AND SHALL REPLACE IT WITH BARS OF THE SAME SIZE AND SPACING, THE SCOPE OF REPAIR AT EACH LOCATION SHALL BE AS SHOWN ON THE PLANS AND APPROVED BY THE ENGINEER PRIOR TO CONSTRUCTION.

 \bullet USE #8 EPOXY-COATED TIE BARS, CONFORMING TO ART. 1006.10 OF THE STANDARD SPECIFICATIONS, FOR ALL TIE BARS.

FILE NAME =	USER NAME = SEYMORECP	DESIGNED -	REVISED -								SECTION	COUNTY	TOTAL SHEETS	SHEET S NO.
c:\pw_work\pwidot\seymorecp\d0348982\D	_work\pwidot\seymorecp\d0348982\DI\$9013-sht-plan.dgn		REVISED -	STATE OF ILLINOIS	TYPICAL REPAIR FOR FULL DEPTH (BARRIER WALL)			VAR.	2013-0411	VARIOUS	44 5			
	PLOT SCALE = 100.0000 '/ in. PLOT DATE = 7/11/2013	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION						CONTRAC	ACT NO. 60	08W06 أ		
Default		DATE -	REVISED -		SCALE:	SHEET	OF	SHEETS STA.	TO STA.		ILLINOIS FEI	. AID PROJECT		