


STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

ROUTE NO.	SECTION	COUNTY	JOB SHEETS	SHEET NO.
F.A.I. 80	*	BUREAU	116	103
FED. ROAD DIST. NO. 7		ILLINOIS FED. AID PROJECT-		


SHEET NO. 25

29 SHEETS


Contract #66623
* (06-1, 2)RS-3, I




TOP PLAN




SOUTH END VIEW



EAST ELEVATION - LOOKING WEST





NORTH END VIEW



WEST ELEVATION - LOOKING EAST

Item	Unit	Total
Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)	Sq. Ft.	0
Epoxy Crack Injection	Foot	0

LEGEND

-  Structural Repair of Concrete ≤ 5"
-  (#') Epoxy Crack Injection w/ Length

DESIGNED	--
CHECKED	JKC
DRAWN	NOE
CHECKED	JKC

CHAMLIN & ASSOCIATES
PERU ILLINOIS MORRIS

FOUNDATION REPAIR PLANS
EASTBOUND
PIER NO. 2
F.A.I. 80 (I-80) OVER DRAINAGE DITCH
SECTION (06-1, 2)RS-3, I
BUREAU COUNTY
SN 006-0009 (EB)
SN 006-0010 (WB)
STA. 423+15