


## DIAPHRAGM REPLACEMENT DETAIL

Pier 3, Span 2 (D11 Beams 1 thru 4) (D12 Beams 5 thru 8)



### DIAPHRAGM REPLACEMENT DETAIL Pier 3, Span 3 (D13)

DESIGNED TLC EXAMINED OCTOBER 16, 2014 CHECKED ATH DRAWN Steffen/baliva
CHECKED TLC ATH REVISED PASSED

# STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

### SECTION COUNTY DIAPHRAGM REPLACEMENT DETAILS EFFINGHAM 63 58B (25-6,7)RS-2 SN 025-0042 CONTRACT NO. 74638 SHEET NO. 11 OF 20 SHEETS

All views are looking East. All dimensions are typical except as noted.

Some beam end repairs not shown for clarity. For beam end repairs, see sheets 8 & 9 of 20. For Table A & Detail A, see sheet 10 of 20. Field drill all holes for diaphragm locations to

# ::XX:::::XX::: ::XX::;;:XX::3 W12x40 "L" (See Table) Beam — −@ Beam

# DIAPHRAGM REPLACEMENT DETAIL

Pier 2 (D8 Span 2) (D9 Span 3)

# match existing.

# :://:::://::: W12x40 2 Bent £ 6" x 4"x 34" x 1'-0" See Detail A. 1 Thus, 1 opposite bend. <u>Ben</u>t ₧ 6" x 4"x ¾" x 1'-0"

# DIAPHRAGM REPLACEMENT DETAIL

"L" (See Table A) | "L" (See Table A) | "L" (See Table A)

East Abutment (D16 Beams 1 thru 4) (D15 Beams 5 thru 8)