


SHOULDER WIDENING AT MAINTENANCE CROSSOVERS



NOTES

- 1.) OMIT RUMBLE STRIPS ON SHOULDERS WITHIN THESE LIMITS.
- 2.) REMOVAL OF EXISTING AGGREGATE SHOULDERS IS INCIDENTAL TO THE COST OF THE PROPOSED 8" HMA BINDER COURSE.

SECTION B-B

482-1

MODEL: det 3_d.tbl
 FILE: \\miller\paw.bentley.com\PI\DOT\Documents\DOT Offices\Dir\dr. 3\Projects-Carcy Detail\03_Detail\03_Surf_CSE_PAVT_REHAB & SHLD.DGN

USER NAME = Anthony.Grunstad	DESIGNED -	REVISED -
	DRAWN -	REVISED -
PLOT SCALE = 100,000 ' / in.	CHECKED -	REVISED -
PLOT DATE = 9/27/23	DATE -	REVISED -

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

SCALE: SHEET OF SHEETS STA. TO STA.

F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
CONTRACT NO.				
ILLINOIS FED. AID PROJECT				