



NORTH PARAPET
Looking North

STRUCTURAL REPAIR

Cost Included in Structural Repair
of Concrete (Depth <5")

PATCH NUMBER	STATION	AREA SQ FT
1	796+69	1.5
2	797+08	17.3
3	797+53	9.0
4	798+75	2.5
5	799+05	11.7
6	799+29	4.0
7	799+49	4.0
8	799+84	6.0
9	799+97	2.0
	Total	58.0