



STRUCTURAL REPAIR

Cost Included in Structural Repair
of Concrete (Depth 45")

PATCH NUMBER	STATION	AREA SQ. FT.
1	51+27	14.0
2	50+88	4.0
3	50+54	6.0
	Total	24.0

SOUTH PARAPET

Looking South

FILE NAME =	USER NAME = swartzrw	DESIGNED -	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	STRUCTURAL REPAIR - PARAPET SN 058-0097		F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
c:\pwwork\pwwid001\SWARTZRW\dms37779\k...enbridge.dgn		DRAWN -	REVISED -		SCALE: N/A	SHEET NO. 7 OF 17 SHEETS	STA.	72	66(B,HVB,HB-1)BR	MACON	83	72
	PLOT SCALE = 28.0000' / IN.	CHECKED -	REVISED -				TO STA.	CONTRACT NO. 74343				
	PLOT DATE = 9/28/2009	DATE -	REVISED -					FED. ROAD DIST. NO.	ILLINOIS FED. AID PROJECT			