


SECTION A-A



SECTION B-B


JOINT REPAIR DETAIL

GENERAL NOTES

PLAN DIMENSIONS AND DETAILS RELATIVE TO EXISTING PLANS ARE SUBJECT TO ROUTINE VARIATIONS. THE CONTRACTOR SHALL FIELD VERIFY EXISTING DIMENSIONS AND DETAILS AFFECTING NEW CONSTRUCTION AND MAKE NECESSARY APPROVED ADJUSTMENTS PRIOR TO CONSTRUCTION OR ORDERING OF MATERIALS. SUCH VARIATIONS SHALL NOT BE CAUSE FOR ADDITIONAL COMPENSATION FOR A CHANGE IN SCOPE OF THE WORK, HOWEVER, THE CONTRACTOR WILL BE PAID FOR THE QUANTITY ACTUALLY FURNISHED BASED UPON THE UNIT PRICE BID FOR THE WORK.

\* COST OF CONCRETE REMOVAL, SAW CUTS & REMOVAL OF EXISTING PJS (4\"/>

FOR SECTION A-A AND B-B SEE SHEET 3 OF 4



END OF SEAL TREATMENT

TOTAL BILL OF MATERIAL		
DESCRIPTION	UNIT	QUANTITY
POLYMER CONCRETE	CU FT	0.9
PROTECTIVE SHIELD	SQ YD	2368
SILICONE JOINT SEALER, 1 3/4"	FOOT	94
SILICONE JOINT SEALER, 2 3/4"	FOOT	188
DECK SLAB REPAIR (PARTIAL)	SQ YD	217
DECK SLAB REPAIR ( FULL DEPTH, TYPE II)	SQ YD	21



Expires Nov. 30, 2010

\* FAP 351 & FAI 294