



DECK PLAN VIEW

BILL OF MATERIAL

Item	Unit	Total
Deck Slab Repair (Partial Depth)	Sq. Yd.	1.0
*Deck Slab Repair (Full Depth, Type I)	Sq. Yd.	2.0

LEGEND

- Concrete Removal for Joint Replacement (See Sheet 6)
- Deck Slab Repair (Partial Depth)

Patch No.	Patch Depth	Station	Length (ft)	Width (ft)	Quantity (sq. yd.)
1	Partial	1616+70.86	3	3	1.00

*Additional Deck Slab Repair (Full Depth, Type I) quantity has been included in the event full depth patches are identified during construction. Location not shown.

3/25/2013 3:59:18 PM - G:\S1\2\0001\Bridges\CAD\Drawings\0243-76F10-05-Deck Patching Plan.dgn

FILE NAME = 0600243-76F10-05-Deck Patching Plan.dgn



USER NAME = ghowley	DESIGNED - SDG	REVISED -
	CHECKED - FAS	REVISED -
PLOT SCALE = 214' 1" / in.	DRAWN - IK	REVISED -
PLOT DATE = 3/25/2013	CHECKED - SDG	REVISED -

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**DECK PATCHING PLAN
STRUCTURE NO. 060-0243 SB**

SHEET NO. 5 OF 10 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
255	60-(8,9) RS-1	MADISON	206	201
CONTRACT NO. 76F10			ILLINOIS FED. AID PROJECT	