


EAST ABUTMENT

Looking East



EAST ABUTMENT
Looking North

ing North

BILL OF MATERIAL

Item	Unit	Total		
Structural Repair of Concrete (Depth < Inches)	Sq. Ft.	14		



Structural Repair of Concrete ≤ 5"

SUBSTRUCTURE REPAIRS

ABUTMENTS

WHITE COUNTY

SN 097-0052 (E.B.)

										•(97-2-1)RS-1; BSMART 2012-1,2,3	
FILE NAME =	USER NAME = halsteadtw	DESIGNED -	REVISED -	STATE OF ILLINOIS	SUBSTRUCTURE REPAIRS			F.A.I.	SECTION	COUNTY SHEETS NO	
c:\pw_work\pwidot\halsteadtw\d0344460\sh	t-pln.dgn	DRAWN -	REVISED -				1	64		WHITE 54 47	
	PLOT SCALE = 8.0000 ' / in.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION	SN 097-0052 (EB)		<u> </u>		CONTRACT NO. 78282		
Default	DLOT DATE - 10/7/2012	DATE	DEVICED		CCALE.	CUEET 21 OF 25 CHEETC CTA	TO CTA		In		