


1 INCIDENTAL BITUMINOUS SURFACING, 6" AVE. THICKNESS

## CONTRACT NO. 76864 COUNTY TOTAL SHEET NO. F.A.P. SECTION 789 54BR-1 MADISON 62 24A STA. TO STA. FED. ROAD DIST. NO. \_ ILLINOIS FED. AID PROJECT





## DETAIL DETECTOR LOOP INSTALLED IN TRENCH

INSTALLATION IS TO BE DONE IN CONFORMANCE WITH THE REQUIREMENTS OF THE PLANS AND SECTION 886 OF THE STANDARD SPECIFICATIONS WITH THE FOLLOWING EXCEPTIONS:

- 1. SLOTS ARE TO BE TRENCHED INSTEAD OF SAWED.
- 2. THIS WORK SHALL NOT BE PAID FOR SEPERATELY BUT SHALL BE INCLUDED IN THE COST OF TEMPORARY BRIDGE TRAFFIC SIGNALS - 1 EACH.

W/ BITUMINOUS SHOULDERS
PRIVATE ENTRANCES





SECTION A-A WITH NEGATIVE GRADE € STA 286+41.3 PE

ILLINOIS DEPARTMENT OF TRANSPORTATION DETAILS SHEET FAP ROUTE 789 SECTION 54BR-1 MADISON COUNTY SCALE: VERT. DRAWN BY DATE CHECKED BY

= 10/18/2096 = c:\projects\ed014 = 50.0000 '/ IN. = \$REF\$ DATE = NAME = SCALE = RENCE = PLOT FILE I PLOT REFER

PLAN