



* Dowel Rods to be grouted after beams are in place and allowed to cure (Min. 24 hr.) prior to grouting the shear keys.

**RAIL POST SPACING AND
SUPERSTRUCTURE DETAILS
IROQUOIS COUNTY
SECTION 08-21119-00-BR
T.R. 212 OVER DRAINAGE DITCH**

SHEET NO.	ROUTE NO.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
SHEET NO. 5	TR 212	08-21119-00-BR	IROQUOIS	24	11
10 SHEETS	S.N. 038-5040		CONTRACT NO. 87501		
FED. ROAD DIST. NO. 7 ILLINOIS			FED. AID PROJECT BR05-0075(147)		