



NOTE:
 IF THE ADJUSTMENT EXCEEDS A 24" HEIGHT THE CONE MUST BE REMOVED AND THE BARREL SECTION HAS TO BE ADJUSTED. THIS WORK SHALL BE PAID FOR UNDER ADDITIONAL MASONRY ITEM.

DETAIL OF TYPE I FRAME ADJUSTMENT

REVISIONS	
NAME	DATE

m:\p\40468\04\1\4-04\19\road_caf\316\51st_drain\9094\516001.dwg 9/26/04 AM