

So-Deep Test Hole **Certification Form** © So-Deep, Inc. 1988, 1991

Control # SILA166
Test Hole # 26
Plan Scale 1"=20"
Sheet # 4
GRADE CHANGE
Date OCTOBER 26, 2006 Condition of paving prior to work NO PAVING


City. County, State Livingston Co., it Gen. Loc. SW CORNER ELM ST. & IL-116 Recorded Size/Material/Type, 8" UNIX. TYPE WATER @ "TEE" Foreman/Truck#/Form By J. HENRY/221/J. HENRY Description: (BM 2) TOP NE MOST BONNET BOLT OF F.H., AT SE CORNER ELM ST. & H.-116


SO-DEEP will alternot to use the BMH most applicable to your design. If however, BMs differ by more than .05, resulting differences could cause design conflicts.


Description: (BM#3) TOP NE MOST BONNET BOLT OF F.H., AT INTR. OF BASS ST. & IL-116

Benchmarks check BY 0.01' Elevations are referenced to B.M.#1 Existing Grade of GRASS RAW Survey Mark PEG (set by SO-DEEP) There WERE NOT additional utilities in the test hole The utility WAS in good condition. /// \\\ Soil Type WET BROWN W/WATER Surveyed Elev. 678.20' Top Util/Struc. Field Condition GRASS R/W SEE BETAIL A Surveyed Elev 6" (I.D.) METALLIC WATER "TEE" Bott. Util/Struc. (if required) OTHER, (SEE REMARKS) Width +

REMAINS: "CREW WAS UNABLE TO DETAIN AN ACCURATE O.D.
MEASUREMENT ON THE METALLLO WATER THE?" DUE TO COPICUS
AMOUNT OF WATER AND INSTABLE OF CHAINED ON THE CENTER
WAS ALSO UNABLE TO GOTANN A ROO READING ON THE CENTER
LINE OF THE "TEE" DUE TO A CORRUGATED METAL STORM PIPE IN
THIS AREA.







SECTION COUNTY TOTAL SHEETS NO. (115)RS-1 LIVINGSTON 279 89

TO STA. FED. ROAD DIST. NO. | ILLINOIS | FED. AID PROJECT

681

CONTRACT NO. 66375



TEST HOLES FAP 681 (IL RTE. 116) SECTION (115)RS-1 LIVINGSTON COUNTY REVISIONS NAME DATE SCALE: VERT. HORIZ. DATE: 3/1/07

DRAWN BY: LANDREY DESIGNED BY: CHECKED BY: BOTT COMPUTER FILE NO. GREENE & BRADFORD, INC. 03145TH9 PROJECT 03145

ILLINOIS DEPARTMENT OF TRANSPORTATION

09/05/07-WCB