

superelevation rate of the pavement exceeds 4%, the shoulder shall be sloped so that the algebraic difference

than 8%.

between pavement and shoulder slopes will not be greater

Michael Brand ENGINEER OF POLICY AND PROCEDURES

January 1,

	1-1-97	Renum. Standard 2429-4.	STANDARD 483001-01
		joint infromation	
		bars and corrected	PCC SHOULDER
	1-1-04	Soft converted metric	
	DATE	REVISIONS	