



NORTH PARAPET
Looking North

STRUCTURAL REPAIR

Cost Included In Structural Repair
of Concrete (Depth <5")

PATCH NUMBER	STATION	AREA SQ FT
1	796+69	1.5
2	797+08	17.3
3	797+53	9.0
4	798+75	2.5
5	799+05	11.7
6	799+29	4.0
7	799+49	4.0
8	799+84	6.0
9	799+97	2.0
	Total	58.0

FILE NAME =	USER NAME = swartzw	DESIGNED -	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	STRUCTURAL REPAIR - PARAPET SN 058-0096 (WB)	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
c:\pw\work\PW100T\SWARTZRW\dca37779\k	enbridge.dgn	DRAWN -	REVISED -			72	66(B,HVB,HB-1)BR	MACON	83	55
	PLOT SCALE = 20,000' / IN.	CHECKED -	REVISED -			CONTRACT NO. 74343				
	PLOT DATE = 9/28/2009	DATE -	REVISED -			SCALE: N/A	SHEET NO. 11 OF 21 SHEETS	STA.	TO STA.	FED. ROAD DIST. NO.