

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SOIL BORING LOG Page 1 of 1
ROUTE FAS 836 DESCRIPTION Bridge Replacement - CH 8 over Little Muddy River
SECTION 07-00077-01-BR LOCATION DuBois Township, SEC. 34, TWP. 33, RNG. 1W
COUNTY Washington, SE 1/4 DRILLING METHOD CME 750/85A HAMMER TYPE Automatic

ROCK CORE LOG Page 1 of 1
ROUTE FAS 836 DESCRIPTION Bridge Replacement - CH 8 over Little Muddy River
SECTION 07-00077-01-BR LOCATION DuBois Township, SEC. 34, TWP. 33, RNG. 1W
COUNTY Washington, SE 1/4 DRILLING METHOD Rocky surface set diameter bit

SOIL BORING LOG Page 1 of 1
ROUTE FAS 836 DESCRIPTION Bridge Replacement - CH 8 over Little Muddy River
SECTION 07-00077-01-BR LOCATION DuBois Township, SEC. 34, TWP. 33, RNG. 1W
COUNTY Washington, SE 1/4 DRILLING METHOD CME 750/85A HAMMER TYPE Automatic

SOIL BORING LOG Page 1 of 2
ROUTE FAS 836 DESCRIPTION Bridge Replacement - CH 8 over Little Muddy River
SECTION 07-00077-01-BR LOCATION DuBois Township, SEC. 34, TWP. 33, RNG. 1W
COUNTY Washington, SE 1/4 DRILLING METHOD CME 750/85A HAMMER TYPE Automatic

SOIL BORING LOG Page 2 of 2
ROUTE FAS 836 DESCRIPTION Bridge Replacement - CH 8 over Little Muddy River
SECTION 07-00077-01-BR LOCATION DuBois Township, SEC. 34, TWP. 33, RNG. 1W
COUNTY Washington, SE 1/4 DRILLING METHOD CME 750/85A HAMMER TYPE Automatic

DESIGNED EML
CHECKED KAK
DRAWN EML
CHECKED KAK

BORING LOGS
STRUCTURE NO. 095-3260



Table with columns: SHEET NO. 11, 11 SHEETS, F.A.S. RTE. 836, SECTION 07-00077-01-BR, COUNTY WASHINGTON, TOTAL SHEETS 27, SHEET NO. 19, CONTRACT NO. 97402, FED. ROAD DIST. NO., ILLINOIS, FED. AID PROJECT