


Notes:

Hatched areas indicate concrete removal.
These areas to be poured after structural
repair of concrete is complete for remainder
of the pier.


For cap removal over non-repair areas, salvage existing #7 vertical bars. Bars to be cleaned, straightened, and incorporated into new construction. Cost included in cost of Concrete Removal.

For cap removal over repair areas, evaluate the existing #7 vertical bars as outlined in the Structural Repair of Concrete Special Provision

Provision. See Sheet 11 of 27 for $v_1(E)$ bar bend information.



V7(E) BARS



u₁ (E) BARS

BILL OF MATERIALS

Bar	No.	Size	Length	Shape		
h ₂ (E)	6	#5	21'-10"			
h3(E)	6	#5	17′-10"			
v ₁ (E)	30	#8	4'-2"			
v ₇ (E)	82	#5	9'-9"			
u ₁ (E)	6	#5	11'-9"			
Concre	te Rem	CU YD	11			
Concre	te Stru	CU YD	18			
	rcement Coated	POUND	1,490			
Epoxy Injecti		FT	7			
of Cor. Equal	ural Rep ocrete (i to or le inches	SQ FT	120			

^{**}Start removal at bottom of existing notch detail

<u>WESTBOUND PIER 2</u> <u>REPAIR DETAILS</u> <u>I-74 OVER LITTLE KICKAPOO CREEK</u> <u>STRUCTURE NO. 057-0121</u>

STRAND ASSOCIATES, INC.

SHEET NO.25	F.A.I. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEET NO.	
	74	(57-21B)BR			MCLEAN	61	37	
27 SHEETS	PIE.	R REPAIR DETA	ILS (4 C	CONTRACT	NO. 70	0641		
	FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT							