







Hanson Professional Services Inc.
 Suite 200, 815 Commerce Drive
 Oak Brook, Illinois 60521
 © Copyright Hanson Professional Services Inc. 2008



SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
① STA 11+91.02	-0.12	0.00	-0.12
② STA 12+15.02	0.00	0.00	-0.12
③ STA 12+39.02	0.12	0.00	-0.12
④ STA 13+11.02	0.48	0.00	-0.48
⑤ STA 16+03.76	0.72	0.00	-0.72



SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
① STA 19+03.76	0.72	0.00	-0.72
② STA 20+30	0.36	0.00	-0.36
③ STA 20+90	0.00	0.00	-0.36
④ STA 21+50	-0.36	0.00	-0.36



SECTION	OFFSET FROM PGL ELEVATION (ft)			
	A	B	C	D
① STA 24+30		-0.36	0.00	-0.36
② STA 24+73.49	-0.6	-0.36	0.00	-0.10
③ STA 24+90	-0.6	-0.36	0.00	0.00