

80% FED, 10% STATE, 10% OP, *** 80% FED, 13% STATE, 7% PP
 OP=VILLAGE OF ORLAND PARK, PP=VILLAGE OF PALOS PARK, STA=STATE
 *=SPECIALTY ITEMS

CONSTRUCTION CODE

CODE NO.	ITEM	UNIT	TOTAL QUANTITY	CONSTRUCTION CODE															
				ROADWAY 80% FED 20% STA 0003	LIGHTING 100% OP 0021	TRAFFIC SIGNALS 135TH 80% FED 20% STA 0021	TRAFFIC SIGNALS SOUTHMOOR 100% OP 0021	TRAFFIC SIGNALS 131ST 80% FED 20% STA 0021	TRAFFIC SIGNALS CREEK *** 0021	TRAFFIC SIGNALS 131ST/HIGH 80% FED 20% STA 0021	INTERCONNECT 80% FED 20% STA 0021	NEW SIDEWALK/ MULTI-USE 80% FED 20% OP 0028	ORLAND PARK 100% 100% OP 0021	NEW SIDEWALK/ MULTI-USE 80% FED 20% PP 0028	PALOS PARK 100% 100% PP 0021	WATER MAIN/SAN SEWER 00% OP 0043	SPECIAL BRIDGE/RET WALL 80% FED 20% STA 0040		
* X0327004	TEMPORARY WOOD POLE, 60 FT., CLASS 4	EACH	5		5														
X0327353	STORMWATER TREATMENT SYSTEM LOCATION NO. 1	L SUM	1	1															
X0327354	STORMWATER TREATMENT SYSTEM LOCATION NO. 2	L SUM	1	1															
X0327374	REMOVAL OF TEMPORARY SOIL RETENTION SYSTEM	SO FT	1180																1180
X0329905	RELOCATE GATE POSTS AND GATE	EACH	1	1															
X2502024	SEEDING, CLASS 4B (MODIFIED)	ACRE	1	1															
X2800400	PERIMETER EROSION BARRIER, SPECIAL	FOOT	1102	1102															
X2800520	ABOVE GRADE INLET FILTERS	EACH	605	605															
X4021000	TEMPORARY ACCESS (PRIVATE ENTRANCE)	EACH	13	13															
X4022000	TEMPORARY ACCESS (COMMERCIAL ENTRANCE)	EACH	15	15															
X4023000	TEMPORARY ACCESS (ROAD)	EACH	5	5															
X4024000	TEMPORARY ACCESS (FIELD ENTRANCE)	EACH	2	2															
X4024100	TEMPORARY ACCESS (WINTERIZE)	SO YD	3642	3642															
X4200110	HIGH-EARLY-STRENGTH PORTLAND CEMENT CONCRETE PAVEMENT 10" (JOINTED)	SO YD	10232	10232															
X4402805	ISLAND REMOVAL	SO FT	2857	2857															

URS
 100 S. WACKER DR.
 SUITE 500
 CHICAGO, IL 60605
 TEL (312) 939-0000
 FAX (312) 939-4198

Rev. 4-17-13