

80% FED, 10% STATE, 10% OP, *** 80% FED, 13% STATE, 7% PP
 OP=VILLAGE OF ORLAND PARK, PP=VILLAGE OF PALOS PARK, STA=STATE
 *=SPECIALTY ITEMS

CONSTRUCTION CODE

CODE NO.	ITEM	UNIT	TOTAL QUANTITY	ROADWAY	LIGHTING	TRAFFIC SIGNALS 135TH	TRAFFIC SIGNALS SOUTHMOOR	TRAFFIC SIGNALS 131ST	TRAFFIC SIGNALS CREEK	TRAFFIC SIGNALS 131ST/HIGH	INTERCONNECT	NEW SIDEWALK/MULTI-USE	ORLAND PARK 100%	NEW SIDEWALK/MULTI-USE	PALOS PARK 100%	WATER MAIN/SAN SEWER	SPECIAL BRIDGE/RET WALL
				80% FED 20% STA	100% OP	80% FED 20% STA	100% OP	80% FED 20% STA	***	80% FED 20% STA	80% FED 20% STA	80% FED 20% OP	100% OP	80% FED 20% PP	100% PP	100% OP	80% FED 20% STA
				0003	0021	0021	0021	0021	0021	0021	0021	0028	0021	0028	0021	0043	0040
* X0327004	TEMPORARY WOOD POLE, 60 FT., CLASS 4	EACH	5		5												
X0327353	STORMWATER TREATMENT SYSTEM LOCATION NO. 1	L SUM	1	1													
X0327354	STORMWATER TREATMENT SYSTEM LOCATION NO. 2	L SUM	1	1													
X0327374	REMOVAL OF TEMPORARY SOIL RETENTION SYSTEM	SO FT	1180														1180
X0329905	RELOCATE GATE POSTS AND GATE	EACH	1	1													
X2502024	SEEDING, CLASS 4B (MODIFIED)	ACRE	1	1													
X2800400	PERIMETER EROSION BARRIER, SPECIAL	FOOT	1102	1102													
X4021000	TEMPORARY ACCESS (PRIVATE ENTRANCE)	EACH	13	13													
X4022000	TEMPORARY ACCESS (COMMERCIAL ENTRANCE)	EACH	15	15													
X4023000	TEMPORARY ACCESS (ROAD)	EACH	5	5													
X4024000	TEMPORARY ACCESS (FIELD ENTRANCE)	EACH	2	2													
X4024100	TEMPORARY ACCESS (WINTERIZE)	SO YD	3642	3642													
X4200110	HIGH-EARLY-STRENGTH PORTLAND CEMENT CONCRETE PAVEMENT 10" (JOINTED)	SO YD	10232	10232													
X4402805	ISLAND REMOVAL	SO FT	2857	2857													

100 S. WACKER DR.
 SUITE 500
 CHICAGO, IL 60606
 TEL (312) 939-1000
 FAX (312) 939-4199
URS