



SN 016-0118
INTERIOR GIRDER REACTION TABLE

		West Abut.	
R_{DL}	(k)	22.0	
R_{LL}	(k)	39.0	
R_I	(k)	10.8	
R_{Total}	(k)	71.8	

BILL OF MATERIAL

SYMBOL	ITEM	UNIT	QUANTITY
	Structural Repair of Concrete, (Depth Equal To or Less Than 5")	Sq. Ft.	144
	Temporary Shoring and Cribbing	Each	3