


PARTIAL FRAMING PLAN - SPANS 14-17



Notes:
 Beams in the North Portion are numbered North to South.
 Beams in the Reversible Portion are numbered North to South.
 Beams in the South Portion are numbered South to North.

LEGEND

- S3.9 Beam Designation
 Indicates North/South/Reversible Portion of Structure
- A Structural Steel Repair Location
- 1 PPC I-Beam Repair Location

COLLINS ENGINEERS
 133 N. Wacker Dr.
 Suite 900
 Chicago, IL 60606
 Tel: (312) 704-9300
 Fax: (312) 704-9320
 www.collinsengr.com
 ILLINOIS PROFESSIONAL DESIGN FIRM LICENSE NO. 184-000993

USER NAME =	DESIGNED - AMS	REVISED -
DRAWN - AMS	CHECKED - JMH	REVISED -
DATE - DECEMBER 2012		

STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION

PARTIAL FRAMING PLAN II
I-90/94 OVER ASHLAND AVE (SN 016-0133)

SHEET NO. 55 OF 534 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
90/94	2012-055BR	COOK	107	69
CONTRACT NO.			60V58	

ILLINOIS FED. AID PROJECT