

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES.

 NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

FILE MOME -	USER NAME + Logica	DESIGNED .	REVISED "	J.A.f. 04-03		CIANING FOR PLEASING OPERATIONS	F.A.U. SECTION COUNTY TOTAL SHEET
Wildentsto/SZxS41coptSutyn		DRAWN -	REVISEO ·	J.A.F. 02-06	STATE OF ILLINOIS	SIGNING FOR FLAGGING OPERATIONS	RTE. SHEETS NO.
i	PLOT SCALE * 59.000 17 IN.	CHECKED -	REVISEO .	S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION	AT WORK ZONE OPENINGS	TC-18 CONTRACT NO. 63743
	STOL BUILD - INSPENDE	DATE -	REVISED	S.P.B. 12-09		SCALE: NONE SHEET NO. 1 OF 1 SHEET'S STA. TO STA.	FED. ROAD DIST, NG. 1 BLUNGIS FED. AND PROJECT