


ILLINOIS APPROACH - SPANS 21 and 22
 (All measurements are along Girder 4 (℄ Roadway))

REPAIRS LIST - SPANS 21 and 22

| I.D. | Description | Pay Item | Units | Quantity |
|------|----------------|----------------------------|---------|----------|
| 071 | Concrete Spall | Deck Slab Repair (Partial) | SQ. YD. | 0.22 |
| 072 | Concrete Spall | Deck Slab Repair (Partial) | SQ. YD. | 0.11 |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |
| - | - | - | - | - |



DECK SLAB REPAIR (PARTIAL)

| | | | | | | | | | | | |
|--------------------|---------------------------------|------------------------------------|---|---|---------------------------|------------|--------------------|--------------|-----------|--|--|
| DESIGNED | EXAMINED | DATE | STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION | REPAIRS TO - DECK SLAB and PARAPETS - SPANS 21 and 22 STRUCTURE NO. 060-0255 | F.A.P. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. | | |
| CHECKED | ENGINEER OF STRUCTURAL SERVICES | | | | 304 | 100B-1DS-1 | MADISON | 58 | 22 | | |
| DRAWN <i>Rad</i> | PASSED | ENGINEER OF BRIDGES AND STRUCTURES | | | SHEET NO. 12 OF 48 SHEETS | | CONTRACT NO. 76E73 | | | | |
| CHECKED <i>MNM</i> | | | | | ILLINOIS FED. AID PROJECT | | | | | | |