


SECTION A-A

**SOUTH ABUTMENT**  
(Looking South)

**LEGEND:**

 Structural Repair of Concrete  
(Depth Equal to or Less Than 5 Inches)

**TOTAL BILL OF MATERIAL**

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)	Sq. Ft.	27

**NOTE:**

No repair work was required for the North Abutment on the Southbound Structure.

FILE NAME = R528252-64E97-16-SB-abut-repairs  
PLOT DATE = 3/29/2010  
PLOT SCALE = 50.0000 1" = 50'

**CHRISTIAN-ROGE & ASSOCIATES, INC.**  
ENGINEERS-PLANNERS-SURVEYORS  
211 WEST WACKER DRIVE  
CHICAGO, ILLINOIS 60606  
PHONE: (312)372-2023 FAX: (312)372-5274

DESIGNED - B.N.S./J.C.N.  
DRAWN - D.L./F.M.  
CHECKED - B.N.S./J.C.N.  
DATE - MARCH, 2010

REVISED -  
REVISED -  
REVISED -  
REVISED -

**STATE OF ILLINOIS**  
**DEPARTMENT OF TRANSPORTATION**

**SOUTH ABUTMENT REPAIRS**  
**SOUTHBOUND STRUCTURE**  
**I-39 OVER U.S. RTE. 30**

**S.N. 052-0052**

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
39	103-1, 103-2/RS	LEE	313	151

SCALE: SHEET NO. 516 OF 528 SHEETS STA. TO STA. CONTRACT NO. 64E97  
FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT