



DECK PLAN

LEGEND:

- Deck Slab Repair (Full Depth, Type I)
- Deck Slab Repair (Full Depth, Type II)
- Joint Reconstruction

NOTE
No Partial-Depth Repairs were Found

NOTES:

- For Joint Reconstruction Details, See Sht's. S5 thru S12.
- For Approach Slab Repairs, See Sht's. S16 thru S23.
- Deck Slab Repair (Partial) is Shown for Information Only.
- Areas of Deck Repairs shown are estimated. The Engineer shall show actual locations of Deck Repairs on As-Built Plans.
- Proposed Overlay to be tapered at Existing Floor Drains, see Detail "A", Sht. S3.
- All Patch dimensions are in feet.
- Diaphragm spacing shown is for reference only.

TOTAL BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Deck Slab Repair (Full Depth, Type I)	Sq. Yd.	6
Deck Slab Repair (Full Depth, Type II)	Sq. Yd.	14

FILE NAME = 0520049-64E97-04-NB-04.plt
 PLOT DATE = 3/29/2010
 PLOT SCALE = 0.0000 1/4" IN.

CHRISTIAN-ROGE & ASSOCIATES, INC.
 ENGINEERS-PLANNERS-SURVEYORS
 211 WEST WACKER DRIVE
 CHICAGO, ILLINOIS 60606
 PHONE: (312)372-2023 FAX: (312)312-5274

DESIGNED - B.N.S./J.C.N.	REVISED -
DRAWN - D.L./F.M.	REVISED -
CHECKED - B.N.S./J.C.N.	REVISED -
DATE - MARCH, 2010	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

DECK PLAN
NORTHBOUND STRUCTURE
I-39 OVER STEWARD CREEK
S.N. 052-0049

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
39	103-1, 103-2/RS	LEE	313	167
CONTRACT NO. 64E97				