



JOINT REPAIR DETAILS S.N. 020-0045









<u>NOTES</u>

REMOVE EXISTING NEOPRENE EXPANSION JOINT AND REPLACE WITH SILICONE JOINT SEALER AND POLYMER CONCRETE NOSING.

REMOVAL OF THE EXISTING NEOPRENE EXPANSION JOINT SHALL BE INCLUDED IN THE COST OF SILICONE JOINT SEALER AND POLYMER CONCRETE.

BILL OF MATERIALS

ITEM	UNIT	TOTAL
SILICONE JOINT SEALER, 2"	FOOT	90.0
POLYMER CONCRETE	CU FT	14.5

FILE NAME =	USER NAME = simsgm	DESIGNED -	-	GMS	REVISED	-	
c:\pw_work\PWIDOT\SIMSGM\d0179794\D5705	31-sht-Bridge Repair Plans.dgn	DRAWN -	-	GMS	REVISED	-	
	PLOT SCALE = 41.6516 ' / IN.	CHECKED -	-		REVISED	-	
	PLOT DATE = 2/19/2010	DATE -	-		REVISED	-	

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

JOINT REPAIR DETAILS		F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.		
	S.N. 020-0045			760	124 BR-1	DEWITT	23	9
	3.it. 020-0043					CONTRAC	T NO.	70531
	SCALE:	SHEET NO. 6 OF 16 SHEETS	STA TO STA	ILLINOIS FED. AID PROJECT				