



March 4, 2021

Page 2

methods to facilitate a stable excavation and prepare the base for the culvert.

If you have any questions regarding this review, please contact Robert Claussen, P.E. at (847)705-4735 or Giancarlo Gierbolini, P.E. at (847) 705-4003.

Cc: IDOT Soil Inspector