



NORTH PARAPET
Looking North

STRUCTURAL REPAIR

Cost Included in Structural Repair
of Concrete (Depth <5')

PATCH NUMBER	STATION	AREA SQ. FT.
1	796+69	1.5
2	797+08	17.3
3	797+53	9.0
4	798+75	2.5
5	799+05	11.7
6	799+29	4.0
7	799+49	4.0
8	799+84	6.0
9	799+97	2.0
	Total	58.0

FILE NAME = c:\projects\74171d\karenbridge.dgn	USER NAME = swartzw	DESIGNED -	REVISED -
		DRAWN -	REVISED -
	PLOT SCALE = 20.0000' / IN.	CHECKED -	REVISED -
	PLOT DATE = 3/20/2008	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

STRUCTURAL REPAIR - PARAPET
SN 058-0096 (WB)

SCALE: N/A SHEET NO. 28 OF 52 SHEETS STA. TO STA.

F.A.I. RTE. 72	SECTION (58,74X66.67)RS-1	COUNTY MACON	TOTAL SHEETS 88	SHEET NO. 53
FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT			CONTRACT NO. 74171	