


IT IS THE CONTRACTOR'S RESPONSIBILITY TO ENSURE THAT NO DAMAGE IS DONE TO THE EXISTING JOINTS AT THE ABUTMENTS DURING MILLING OPERATIONS. ANY DAMAGE TO THE POLYMER CONCRETE OR SILICONE JOINT SEALER DURING REMOVAL OPERATIONS MUST BE REPAIRED BY THE CONTRACTOR AT HIS EXPENSE TO THE SATISFACTION OF THE ENGINEER.

SEE SHEET 11 FOR ADDITIONAL INFORMATION ON JOINT



FILE NAME =	USER NAME = \$USER\$	DESIGNED - _____	REVISED - _____	<b>STATE OF ILLINOIS</b> <b>DEPARTMENT OF TRANSPORTATION</b>	<b>SN 032-0075 DECK DRAIN INFORMATION/DETAILS</b>	F.A.S. RTE. 297	SECTION IG-VBIRS-1 & (FIRS-4	COUNTY GRUNDY	TOTAL SHEETS 15	SHEET NO. 12	
*FILEL\$	PLOT SCALE = \$SCALE\$	CHECKED - _____	REVISED - _____			<b>CONTRACT NO. 66080</b>					
*MODELNAME\$	PLOT DATE = \$DATE\$	DATE - _____	REVISED - _____			ILLINOIS FED. AID PROJECT					
						SCALE: _____ SHEET _____ OF _____ SHEETS STA. _____ TO STA. _____					