

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION CONSULTING ENGINEERS Chicago, Illinois 312.228.0100 www.bbandainc.com CHECKED - BAK REVISED PLOT SCALE = DRAWN - MTR REVISED PLOT DATE =03/29/2013 CHECKED - IYL REVISED

SHEET NO. S-14 OF S

Concrete Removal

Structural Repair of Concrete (Depth greater than 5 inches)

## BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth equal to or less than 5 inches)	Sq. Ft.	58
Structural Repair of Concrete (Depth greater than 5 inches)	Sq. Ft.	3
Epoxy Crack Injection	Foot	3
Concrete Removal	Cu. Yd.	35

NGWALL REMOVAL & REPAIR – SN 016–2442	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
STRUCTURE NOS. 016–2441 & 016–2442	94	2012-059-BR	СООК	631	570	
			CONTRACT	「 NO.	60J12	
SHEET NO. S-14 OF S-31 SHEETS		ILLINOIS FED. AID PROJECT				