



PARTIAL PLAN

Notes: For details of Deck Slab Repair see Special Provision for "Deck Slab Repair."

See Sheet #6 of 8 for Cross Section.

For Sec. A-A see Sheet #3 of 8.

The quantities shown for estimating purposes only. Area to be repaired will be determined by the Engineer at the time of Construction. Actual repair locations shall be shown on the same as-built plans.

LEGEND

- * Deck Slab Repair (Full Depth, Type I) (In areas with planks)
- Structural Repair of Concrete (Depth equal to or less than 125 mm)

* Paid for as indicated on sheet 6 of 7.

BILL OF MATERIAL

Item	Unit	Total
Deck Slab Repair (Full Depth, Type I)	Sq. M	0.4
Structural Repair of Concrete (Depth equal to or less than 125 mm)	Sq. M	0.1
Silicone Joint Sealer, 25 mm	Meter	27

Deck Survey Date: 11/22/04

LIN ENGINEERING, LTD.
 20 W. Chestnut
 62511-483-1668
 Chatham, Illinois 62629
 Fax: (201) 483-4706
 Designed By: STD
 Checked By: JTW
 Drawn By: JMD
 Date: 01/02
 File: 047048.004

REVISIONS	
NAME	DATE

ILLINOIS DEPARTMENT OF TRANSPORTATION
DECK REPAIR-4
F.A.P. 326 (IL RTE. 47)
OVER FOX RIVER
SECTION (108,109)RS-4
KENDALL COUNTY
S.N. 047-0048