



CROSS SECTIONS
 ALIGNMENT 500
 500+12 - 502+39

REHABILITATE NORTH HANGAR PAVEMENTS,
 IDA No. LOT-4020 AIP No. 3-17-0140-B48



Copyright Hanson Professional Services Inc. 2011
Hanson Professional Services Inc.
 815 Commerce Drive Suite 200
 Oak Brook, Illinois 60523

Hanson No. 10A0072
 Filename 28-CROSS SECTIONS 500-1.DWG
 Scale 1"=20'
 Date APRIL 22, 2011

LAYOUT	KMS	02/22/11
DRAWN	KMS	02/22/11
REVIEWED	RMH	4/22/11

Chicago-Romeoville Airport
JOLIET REGIONAL PORT DISTRICT
 1 George Michas Drive
 Romeoville, Illinois 60446
 Telephone: 815.838.9497
 Fax: 815.838.9524

DATE	REVISION