



NOTE: PRC FLARED END SECTION SHOWN.
TREATMENT SAME FOR OTHER
END SECTIONS.

DETAIL OF EROSION CONTROL BLANKET LINING AROUND END SECTION