

• (1-5)RS-1; (1-6)RS CONTRACT NO. 72694



PROPOSED LONGITUDINAL JOINT REPAIR DETAIL (TYPICAL)



NOTE : THE ENGINEER IN THE FIELD SHALL DETERMINE AND LOCATE ALL AREAS FOR REPAIR

[REVISIONS DATE		ILLINOIS DEPARTMENT OF TRANSPORTATION	
Ļ				
- 1				
- 1			LONGITUDINAL JOINT REPAIR & SILICONE JOINT SEALER DETAILS	
ŀ				
ŀ				
f				
[SCALE: VERT.	DRAWN BY JJS
L			HORIZ.	
			DATE 09/10/2004	CHECKED BY LLQ