
-CABLE JACKET REMOVED, "PENCIL" INSULATION. CONTRACTOR SHALL USE A CABLE STRIPPER/PENCILLER WHENEVER CABLE

CONNECTIONS ARE MADE.



3. DEPTH OF TRENCHES SHALL BE AS SHOWN ABOVE UNLESS OTHERWISE SPECIFIED ON THE PLANS.


4. ALL DISTURBED SURFACES SHALL BE RESTORED TO THEIR ORIGINAL CONDITION. COST IS INCIDENTAL TO TRENCH.

## **CABLE TRENCHES**

(NOT TO SCALE)

CABLES INSIDE UNIT DUCT AS SHOWN ON PROPOSED


LIGHTING LAYOUT SHEET(S)



- 1. TUBULAR REFLECTIVE MARKER (TRM) SHALL COMPLY WITH FAA AC 150\5345-39.
- TUBULAR REFLECTIVE MARKER TO BE INSTALLED PER MANUFACTURER'S INSTRUCTION.

## TAXIWAY REFLECTIVE MARKER (TRM)

(NOT TO SCALE)



PLASTIC BODY MOLD-

FEB 20, 2013 2:27 PM HAUSM00682

27

27 of 32 shee

CONSTRUCT APRON AND TAXIWAY IN SOUTH FRONTAL AREA

A HANSON