

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2006-9
Various Counties
Sheet 9 of 114
Contract Number 44904

District 1
Schedule of Locations for Truss Repair & Replacement

Location No.:	1-01	State I.D. No.:	1C016I290R018.8 (CLE-1)P2				
County:	Cook	Route:	I-290	M.P.:	18.8	Direction:	EB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	19.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-02	State I.D. No.:	1S016I290R020.0 (TRE-3)O4				
County:	Cook	Route:	I-290	M.P.:	20	Direction:	EB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00					
FURNISH & INSTALL HANDRAIL	Foot	47.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-03	State I.D. No.:	1C016I290R021.0 (CLE-2)N2				
County:	Cook	Route:	I-290	M.P.:	21	Direction:	EB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	21.50					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-04	State I.D. No.:	1C016I290R023.4 (C-8)L4				
County:	Cook	Route:	I-290	M.P.:	23.4	Direction:	EB
Description of Work	Unit	Quantity					
FURNISH & INSTALL HANDRAIL	Foot	24.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-05	State I.D. No.:	1C016I290R027.3-0 (CLE-2)H2				
County:	Cook	Route:	I-290	M.P.:	27.3	Direction:	EB
Description of Work	Unit	Quantity					
FURNISH & INSTALL HANDRAIL	Foot	24.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-06	State I.D. No.:	1C016I290R028.4 (CLE-1)H8				
County:	Cook	Route:	I-290	M.P.:	28.4	Direction:	EB
Description of Work	Unit	Quantity					
FURNISH & INSTALL HANDRAIL	Foot	35.50					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-07	State I.D. No.:	1S016I290L014.2 (TW-4)X1				
County:	Cook	Route:	I-290	M.P.:	14.2	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00					
FURNISH & INSTALL HANDRAIL	Foot	63.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-08	State I.D. No.:	1S016I290L018.0 (TRW-2)R1				
County:	Cook	Route:	I-290	M.P.:	18.0	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00					
FURNISH & INSTALL HANDRAIL	Foot	78.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-09	State I.D. No.:	1C016I290L019.4 (CLW-5)P3				
County:	Cook	Route:	I-290	M.P.:	19.4	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	19.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-10	State I.D. No.:	1C016I290L019.8 (CLW-4)O1				
County:	Cook	Route:	I-290	M.P.:	19.8	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	17.50					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-11	State I.D. No.:	1S016I290L020.7 (TRW-1)N3				
County:	Cook	Route:	I-290	M.P.:	20.7	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00					
FURNISH & INSTALL HANDRAIL	Foot	43.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-12	State I.D. No.:	1S016I290L023.0 (TRW-9)L1				
County:	Cook	Route:	I-290	M.P.:	23	Direction:	WB
Description of Work	Unit	Quantity					
FURNISH & INSTALL HANDRAIL	Foot	56.50					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-13	State I.D. No.:	1C016I290L023.0 (CLW-3)K7				
County:	Cook	Route:	I-290	M.P.:	23	Direction:	WB
Description of Work	Unit	Quantity					
FURNISH & INSTALL HANDRAIL	Foot	24.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-14	State I.D. No.:	1C016I290L027.6 (CLW-2)H7				
County:	Cook	Route:	I-290	M.P.:	27.6	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	23.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-15	State I.D. No.:	1C016I290L028.7 (CLW-1)H1				
County:	Cook	Route:	I-290	M.P.:	28.7	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00					
FURNISH & INSTALL HANDRAIL	Foot	23.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-16	State I.D. No.:	1S022I055L273.2 (TRS-10)D1				
County:	DuPage	Route:	I-55	M.P.:	273.2	Direction:	SB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	Each	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	Each	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	Each	1.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	4.00					
FURNISH & INSTALL SAFETY CHAIN	Each	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	Each	4.00					
OVERHEAD SIGN STRUCTURE WALKWAY	Foot	88.00					
This work shall be completed during District 1 night-time hours.							

Location No.:	1-17	State I.D. No.:	1S022I055R272.7 (TRN-8)D2				
County:	DuPage	Route:	I-55	M.P.:	272.7	Direction:	SB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	Each	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	Each	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	Each	1.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	4.00					
FURNISH & INSTALL SAFETY CHAIN	Each	2.00					
REPAIR CONCRETE FOUNDATION FOR OVERHEAD SIGN STRUCTURE	Each	1.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	Each	4.00					
OVERHEAD SIGN STRUCTURE WALKWAY	Foot	88.00					
This work shall be completed during District 1 night-time hours.							