## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Various Routes OVD SIN STR REP & REPL 2006-9 Various Counties Sheet 39 of 114 Contract Number 44904

District 3
Schedule of Locations for Overhead Sign Structure Replacement

Location No.:	3-04	State I	D. No.:		350	50103	9R058.3	
County:	LaSalle	Route:	1-39	Direction: NB				
Description of	Work						Unit	Quantity
REMOVE OV	ERHEAD SIGN	STRU	CTURE-	SPAN	1		EACH	1.00
OVERHEAD S	SIGN STRUCT	URE-SF	PAN, TYI	PEII	Α		FOOT	124.00
REMOVE & R	EINSTALL SIG	N PAN	EL				SQ FT	413.25
REMOVE & R	EINSTALL WA	LKWAY	/				FOOT	49.00
OVERHEAD S	SIGN SUPPOR	T GRO	JT REP	۹IR			EACH	4.00
FURNISH & INSTALL SAFETY CHAIN						EACH	2.00	
DISCONNEC	T/RECONNEC	T ELEC	TRIC SE	RVIC	Œ.		EACH	1.00
This structure	is being downs	ized fro	m a Typ	e IV t	truss to a	э.		
Type II truss.								

p.,,,,								
Location No.:	3-05	State I.D. No.:		38	0501-3			
County:	LaSalle	Route: I-39 M.P.: 60.3				Direc	tion: SB	
Description of	Unit	Quantity						
REMOVE OVE	REMOVE OVERHEAD SIGN STRUCTURE-SPAN							
OVERHEAD SIGN STRUCTURE-SPAN, TYPE II-A							108.00	
REMOVE & REINSTALL SIGN PANEL							298.25	
REMOVE & REINSTALL WALKWAY							52.00	
FURNISH & INSTALL SAFETY CHAIN							2.00	
OVERHEAD SIGN SUPPORT GROUT REPAIR							4.00	
DISCONNECT/RECONNECT ELECTRIC SERVICE							1.00	
This structure is	s being downsize	ed from a	Type IV tru	ss to a				
Type II truss.								

Location No.:	3-01	State I.D. No.:		35	3050103	39L059.6	
County:	LaSalle	Route:	Route: I-39 M.P.: 59.6			Direc	tion: SB
Description of Work							Quantity
REMOVE OVE	REMOVE OVERHEAD SIGN STRUCTURE-SPAN						
OVERHEAD S	IGN STRUCTUR	E-SPAN	, TYPE II-A			FOOT	108.00
REMOVE & REINSTALL SIGN PANEL						SQ FT	342.50
REMOVE & REINSTALL WALKWAY							31.00
OVERHEAD SIGN SUPPORT GROUT REPAIR						EACH	4.00
FURNISH & INSTALL SAFETY CHAIN							2.00
DISCONNECT/RECONNECT ELECTRIC SERVICE						EACH	1.00
	s being downsize	ed from a	Type IV trus	s to a			
Type II truss.			***************************************				

Location No.:	3-02	State I.D. No.:		3S050I039R057					
County:	LaSalle	Route:	I-39	M.P.:	57.7	7.7 Direction: N			
Description of Work							Quantity		
REMOVE OVE	RHEAD SIGN S	TRUCTUR	E - SPAN			EACH	1.00		
OVERHEAD SI	OVERHEAD SIGN STRUCTURE-SPAN, TYPE II-A								
REMOVE & REINSTALL SIGN PANEL							299.00		
REMOVE & REINSTALL WALKWAY							44.00		
OVERHEAD SIGN SUPPORT GRPOUT REPAIR							4.00		
DISCONNECT/RECONNECT ELECTRIC SERVICE							1.00		
This structure is	s being downsiz	ed from a T	ype IV trus	ss to a					
Type II truss.									

Location No.:	3-03	State I.D. No.:		38	050103	39R057.2		
County:	LaSalle	Route:	I-39	M.P.:	57.2	Direc	tion: NB	
Description of	Unit	Quantity						
REMOVE OVE	EACH	1.00						
OVERHEAD SI	GN STRUCTUR	RE-SPAN, T	TYPE II-A			FOOT	124.00	
REMOVE & REINSTALL SIGN PANEL							299.00	
REMOVE & REINSTALL WALKWAY							44.00	
OVERHEAD SIGN SUPPORT GROUT REPAIR							4.00	
FURNISH & INSTALL SAFETY CHAIN							2.00	
DISCONNECT/RECONNECT ELECTRIC SERVICE							1.00	
This structure is	s being downsize	ed from a T	ype IV trus	ss to a				
Type II truss.								