

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2006-9
Various Counties
Sheet 74 of 114
Contract Number 44904

District 6
Schedule of Locations for Truss Repair & Replacement

Location No.:	6-01	State I.D. No.:	6S0751072L004.9		
County:	Pike	Route:	I-72	M.P.:	4.9
				Direction:	WB
Description of Work		Unit	Quantity		
REMOVE OVERHEAD SIGN STRUCTURE-SPAN		EACH	1.00		
OVERHEAD SIGN STRUCTURE-SPAN TYPE II-A		FOOT	104.00		
REMOVE & REINSTALL SIGN PANEL		SQ FT	468.00		
REMOVE & REINSTALL WALKWAY		FOOT	59.00		
REPAIR HANDRAIL LOCKING PIN CONNECTION		EACH	6.00		
FURNISH & INSTALL SAFETY CHAIN		EACH	2.00		
FURNISH & INSTALL METAL SCREEN		EACH	4.00		
DISCONNECT / RECONNECT ELECTRIC SERVICE		EACH	1.00		
REPLACE/TIGHTEN CLIP PER SIGN		EACH	1.00		
This structure is being downsized from a Type IV truss to					
a Type II truss.					