STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Various Routes OVD SIN STR REP & REPL 2006-9 Various Counties Sheet 104 of 114 Contract Number 44904

District 8 Schedule of Locations for Truss Repair & Replacement

Location No.: 8-01	State I.D. No.: 8S060I05		5L017.2			
County: Madison	Route:	I ~ 55	M.P.:	17.2	Direction: W	
Description of Work						Quantity
REMOVE OVERHEAD SIGN STRUCTURE-SPAN						1.00
OVERHEAD SIGN STRUCTURE - SPAN, TYPE II A					FOOT	80.00
FURNISH & INSTALL METAL SCREEN					EACH	4.00
DISCONNECT / RECONNECT ELECTRIC SERVICE					EACH	1.00
REMOVE & REINSTALL SIGN PANEL					SQ FT	472.50
REMOVE & REINSTALL WALKWAY					FOOT	39.00
This truss is being downsized	from a T	ype IV tru:	ss to a			
Type II truss. The existing er	nd suppor	ts will be ι	ısed.			
All work must be completed dur	ng District	8 non-pea	k hours.			

Location No.: 8-02	State I.D	State I.D. No.:		8S082S003L004.4		
County: St. Cl	air Route:	IL - 3	M.P.:	4.4	Direc	tion: SB
Description of Work		•••••			Unit	Quantity
REMOVE OVERHEAD	SIGN STRUCTUR	E - SPAN			EACH	1.00
OVERHEAD SIGN STRUCTURE - SPAN TYPE IIA					FOOT	84.00
OVERHEAD SIGN SUPPORT GROUT REPAIR					EACH	4.00
FURNISH & INSTALL SAFETY CHAIN					EACH	2.00
DISCONNECT / RECONNECT ELECTRIC SERVICE					EACH	1.00
REMOVE & REINSTA	LL SIGN PANEL				SQ FT	377.00
REMOVE & REINSTA	LL WALKWAY				FOOT	44.50
This truss is being d	ownsized from a T	ype IV tru	iss to a			
Type II truss. The exis	sting end supports w	ill be used	•			
All work must be comp	eted during District	8 non-pea	k hours.			

Location No	o.: 8 - 03	State I.D	State I.D. No.: 8S06010			55L018.3		
County:	Madison	Route:	1 - 55	M.P.:	18.3	Direc	tion: WB	
Description	of Work			······································		Unit	Quantity	
REMOVE OVERHEAD SIGN STRUCTURE - SPAN						EACH	1.00	
OVERHEAD SIGN STRUCTURE - SPAN, TYPE II A					FOOT	70.00		
FURNISH & INSTALL METAL SCREEN					EACH	4.00		
DISCONNECT / RECONNECT ELECTRIC SERVICE						EACH	1.00	
REMOVE & REINSTALL SIGN PANEL						SQ FT	336.00	
REMOVE & REINSTALL WALKWAY					FOOT	42.00		
This truss is	s being downsize	ed from a T	ype IV trus	s to a				
Type II trus	s. The existing	end suppor	ts will be u	sed.				
All work mus	st be completed du	uring District	8 non-peak	hours.				