## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2005-12
Various Counties
Sheet 34 of 82
Contract Number 44872

## District 3 Schedule of Locations for Truss Repair & Replacement

Location	No.:	3-01	State I.D	State I.D. No.: 3S057I05			55L000.9		
County:		McLean	Route:	I-55 M.P.: 0.9 Direction: S					
Description of Work								Quantity	
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN								1.00	
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE								2.00	
FURNISH & INSTALL SADDLE SHIM BLOCK								4.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER								1.00	
FURNISH & INSTALL SAFETY CHAIN								2.00	
OVERHEAD SIGN STRUCTURE WALKWAY								72.00	
REMOVE CONCRETE FOUNDATION-OVERHEAD							EACH	2.00	
DRILLED SHAFT CONCRETE FOUNDATION							CU YD	21.60	
RELOCATE ELECTRIC SERVICE								1.00	

Location	No.:	3-04	State I	.D. No.:	,	3S057I074R133.9				
County:		McLean	Route:	1-74	M.P.:	133.9	Direction: EB			
Description of Work								Quantity		
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE - SPAN								1.00		
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE								2.00		
FURNISH & INSTALL SADDLE SHIM BLOCK								4.00		
FURNISH & INSTALL INTERNAL TRUSS DAMPER								1.00		
FURNISH & INSTALL SAFETY CHAIN								2.00		
OVERHEAD SIGN STRUCTURE WALKWAY								68.50		
REMOVE CONCRETE FOUNDATION - OVERHEAD								2.00		
DRILLED SHAFT CONCRETE FOUNDATIONS								21.60		
RELOCATE ELECTRIC SERVICE								1.00		

Location	No.:	3-02	State I	.D. No.:	3	S057107	74L134.8		
County:		McLean	Route:	I-74	M.P.:	134.8			
Descripti	on of V	Vork					Unit	Quantity	
REMOVE	EACH	1.00							
STRUCT	STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE								
OVERHEAD SIGN STRUCTURE-SPAN TYPE I-A								50.00	
REMOVE & REINSTALL WALKWAY								36.00	
REMOVE & REINSTALL SIGN PANEL							SQ FT	313.75	
FURNISH & INSTALL SAFETY CHAIN								2.00	
REMOVE CONCRETE FOUNDATION-OVERHEAD								2.00	
DRILLED SHAFT CONCRETE FOUNDATION							CU YD	12.00	
RELOCATE ELECTRIC SERVICE							EACH	1.00	
		·							
This sign	structur	re is being compl	etely replac	ced.					

Location	No.:	3-03	State I.I	State I.D. No.: 3S057I07				***************************************
County:		McLean	Route:	I-74	M.P.:	135.7	Direc	tion: WB
Descripti	Unit	Quantity						
REMOVE		EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE								2.00
FURNISH & INSTALL SADDLE SHIM BLOCK								4.00
FURNISH & INSTALL INTERNAL TRUSS DAMPER								1.00
FURNISH & INSTALL SAFETY CHAIN								2.00
OVERHEAD SIGN STRUCTURE WALKWAY								76.33
REMOVE CONCRETE FOUNDATION-OVERHEAD								2.00
DRILLED SHAFT CONCRETE FOUNDATION								21.60
RELOCATE ELECTRIC SERVICE								1.00