



NOTES:

1. COORDINATE WORK ON THIS SHEET WITH DRAINAGE AND UTILITY PLANS.
 2. RESTORATION OF DISTURBED SOIL SHALL BE SEEDED WITH CLASS "3" ON SLOPES AND CLASS "4 MODIFIED" AND "5 MODIFIED" ON BASIN FLOOR.
- MANHOLE WITH RESTRICTOR PLATE STA. 154+04, 95' LT. RIM 665.0 INV 659.43 (OUTLET PIPE) SEE RESTRICTOR PLATE DETAIL SHEET FOR ADDITIONAL DETAILS
 - SPECIAL HEADWALL, SEE HEADWALL DETAIL STANDARD 542116-02 FOR ADDITIONAL DATA

24,999 / IN. 1/20/2011 K:\117702\CAD\Sheets\177702_Basin_Jericho_Lake.dgn

rjngroup
Excellence through Ownership
200 West Front Street
Wheaton, IL 60187

WBK WILLS BURKE KELSEY ASSOCIATES LTD.
116 West Main Street, Suite 201
St. Charles, Illinois 60174
(830) 443-7755

DESIGNED - MK	REVISED -
DRAWN - DW	REVISED -
CHECKED - MH	REVISED -
DATE - 12/20/2010	REVISED -

KANE COUNTY
DIVISION OF TRANSPORTATION
ORCHARD ROAD RECONSTRUCTION

JERICO LAKE DETENTION AND COMPENSATORY STORAGE BASINS

SCALE: 1" = 30' SHEET NO. 3 OF 3 SHEETS STA. TO STA.

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
336	99-00232-01-WR	KANE	215	73
CONTRACT NO. 63541			ILLINOIS FED. AID PROJECT	