



**PARTIAL PLAN**

Notes: For details of Deck Slab Repair see Special Provision for "Deck Slab Repair."  
 See Sheet #6 of 8 for Cross Section.  
 For Sec. A-A see Sheet #3 of 8.  
 The quantities shown for estimating purposes only. Area to be repaired will be determined by the Engineer at the time of Construction. Actual repair locations shall be shown on the same as-built plans.

**LEGEND**

- Deck Slab Repair (Full Depth, Type I) (In areas without planks)
- \* ☒ Deck Slab Repair (Full Depth, Type I) (In areas with planks)
- ▨ Structural Repair of Concrete (Depth equal to or less than 125 mm)

\* Paid for as indicated on sheet 6 of 7.

**BILL OF MATERIAL**

Item	Unit	Total
Deck Slab Repair (Full Depth, Type I)	Sq. M	1.2
Structural Repair of Concrete (Depth equal to or less than 125 mm)	Sq. M	0.2
Silicone Joint Sealer, 25 mm	Meter	54

Deck Survey Date: 11/22/04

**LIN ENGINEERING, LTD.**  
 220 W. Chestnut  
 Chicago, Illinois 60629  
 (312) 467-8888 FAX (312) 467-8774  
 Designed By: STD Checked By: MTH Drawn By: JMD  
 Date: 01/05 File: 0470048.DGN

REVISIONS	
NAME	DATE

ILLINOIS DEPARTMENT OF TRANSPORTATION  
**DECK REPAIR-3**  
**F.A.P. 326 (IL RTE. 47)**  
**OVER FOX RIVER**  
**SECTION (108,109)RS-4**  
**KENDALL COUNTY**  
**S.N. 047-0048**