



## TIE BEAM UNDERSIDE PLAN



## PIER 8 - EAST ELEVATION

(Dimensions taken from existing drawings)



## PIER 9 - WEST ELEVATION

(Dimensions taken from existing drawings)

Note: Contractor shall verify limits of unsound concrete shown prior to beginning repair.

BILL OF MATERIAL

	ITEM		UNIT	QUANTITY
Structural Repair of	Concrete (Depth	Equal To or Less Than 5")	Sq. Ft.	501

									,	í .
FILE NAME =	USER NAME =	DESIGNED - BTO:	REVISED -		PIER: 8: &: PIER: 9: SUBSTRUCTURE: REPAIR: EB:	F.A.I. SEC	CTION	COUNT	TOTAL SHEET	ř.
		CHECKED: RAB	REVISED -	STATE: OF ILLINOIS:		474	penp	31 A 9 TA 75 WE	SHEETS NO.	į.
Ř.	PLOT SCALE =	DRAWN: - BTO	REVISED: -	DEPARTMENT OF TRANSPORTATION	STRUCTURE: NO: 090-0108		T E GIT	CONTRA	CT NO 68069	i.
t	PLOT DATE =	CHECKED - RAB	REVISED -		SHEET NO. 63 OF 65 SHEETS	1	ILLINOIS FED.	AID PROJECT	<u> </u>	Ė