

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2008-9
Various Counties
Sheet 94 of 105
Contract Number 44973

District 8
Schedule of Overhead Sign Structure Repair & Replacement

Location No.:	8-01	State I.D. No.:	8S060I270L004.4				
County:	Madison	Route:	I-270	M.P.:	4.4	Direction:	WB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
DISCONNECT/RECONNECT ELECTRIC SERVICE	EACH	1.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	92.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00					

Location No.:	8-04	State I.D. No.:	8S067S003R018.1				
County:	Randolph	Route:	IL 3	M.P.:	18.1	Direction:	NB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE - SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUSTURE	EACH	2.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	80.00					
FURNISH & INSTALL TRUSS DAMPER	EACH	1.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
REPLACE U-BOLT	EACH	4.00					

Location No.:	8-02	State I.D. No.:	8S060S159R003.8				
County:	Madison	Route:	II 159	M.P.:	3.8	Direction:	NB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE - SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
OVERHEAD SIGN STRUCTURE WAKWAY	FOOT	82.00					
REPLACE U-BOLT	EACH	4.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00					

Location No.:	8-05	State I.D. No.:	8S082I064R018.4				
County:	St. Clair	Route:	I - 64	M.P.:	18.4	Direction:	EB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	3.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	107.00					
OVERHEAD SIGN STRUCTURE GROUT REPAIR	EACH	4.00					

Location No.:	8-03	State I.D. No.:	8S060I055R014.3				
County:	Madison	Route:	I-55	M.P.:	14.3	Direction:	NB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE - SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
REPLACE /TIGHTEN CLIPS PER SIGN	EACH	2.00					
OVERHEAD SIGN STRUCTURE EALKWAY	FOOT	67.00					

Location No.:	8-06	State I.D. No.:	8S082S015L013.6				
County:	St. Clair	Route:	IL 15	M.P.:	13.6	Direction:	WB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
REPLACE U-BOLT	EACH	4.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	76.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
CONCRETE FOUNDATION REPAIR FOR OSS	EACH	2.00					