



Note: Existing reinforcement extending into new construction shall be cut off flush. Cost included with Concrete Removal.

- LEGEND**
- Concrete Removal
 - Structural Repair of Concrete (Depth equal to or less than 5")
 - ±5" Epoxy Crack Injection
 - H.L.C. Hairline Crack (Not to be Sealed)

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Concrete Removal	Cu. Yd.	2.8
Epoxy Crack Injection	Foot	6
Structural Repair of Concrete (Depth Equal To Or Less Than 5")	Sq. Ft.	11.2

PIER 1 REMOVAL AND REPAIR
F.A.P. ROUTE 317 (U.S. 24)
OVER OTTER CREEK
SECTION (18B)I
FULTON COUNTY
STATION 257+54.33
STRUCTURE NO. 029-0005

PLT DATE = #DATES
 DATE = #DATES
 FILE NAME = #MODELNAME